

~~3229~~

order of passage.
Addressed in Jan^{ry} 18

11.65

Bottom cleaned and coated with Red Lead and
the vessel scraped and painted throughout

Treenails	Windlass and Capstan
-----------	----------------------

Good P.T.O.

How to where you

M. L. Lorne's

26

1826

10088

Joan

The two Engines and Boilers were put in when
lying in the River prior to her being docked for Survey
and before any order for Survey was left. but the
parts as far as could be examined were found to
be in good condition.

McLurcan



© 2019

Lloyd's Register
Foundation