

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 3541** Survey held at **Glasgow** Date, first Survey **27th Aug** Last Survey **2nd Sept** 18**72**
 on the **S.S. "Alexandra"** Master **Burill**

581 Tonnage **437** built at **Stockton** When built **1863**
363 By whom built **Richardson** Owners **Palgrave & Murphy**

Port belonging to **Dublin** Destined Voyage **Glasgow to Porto**

If Surveyed Afloat or in Dry Dock **Tod & McGeorg's Patent Slipway**

Last Survey, No. **8799** Port **Irish** Classed **(S.S. Dub. No. 241) 1/3/71**

REPAIRS, &c.

Seven outside Butt straps on Port side midships and five on the Starboard side, and one plate on turn of Bilge doubled. Bottom coated with paint.

Present Condition of the

Decks	Freeboards Rails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails As before
Sheerstrakes	Clamps and Shelves	Anchors No. of do
Topsides	Ceiling	Cables do
Wales	Rudder	Hawsers and Warps Good
Plank (Bottom) and Counter	Copper Paint When put on 1872	Standing & Running Rigging Good
Engine Room Skylights Good	Caulking of	
Coal Bunker, Openings, Lids, &c. Good	Bottom, Deck, & Waterways Good	
Scuppers Good	Cargo and Main Hatchways Good	Hatches Good
General Observations and Opinion, In good and efficient condition and eligible to remain as claps		

The Amount of Entry Fee.....£ : : : is received by me,

Special.....£ : : :

Certificate (if required) : : :

Committee's Minute **13th September 1872**

Character assigned **A**