

REPORT of SURVEY for REPAIRS.

Rev 12/4/78

No. in Reg. Book. 47 No. 10547 Survey held at Sunderland Date, first Survey 28th Janu^y Last Survey 28th Sept 1873
on the Iron SS Achilles Master Jones

Tonnage 1426 built at Sunderland When built 1865

By whom built Jas Laing Owners Jenwick & Co

Port belonging to London Destined Voyage _____

If Surveyed Afloat or in Dry Dock Dry Dock

10645

Last Survey, No. 10547 Port Sunderland Classed 90 A

S.S. No. 272

REPAIRS, &c.

At the present time damage & additional Repairs. Broken propeller renewed, part of the Main Deck ditto yellow & pitch Pine. Gunwale Stinger plate doubled in midship part of the vessel for about 40 feet in length with 8/16 plating. Bottom coated with Paint

Present Condition of the

Decks	Greenalls Rivets	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats <u>5</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>Good & sufficient</u>
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>3 Bar. St. V. Rings</u> <u>where they could be seen</u>
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper	Standing & Running Rigging
Engine Room Skylights <u>Good</u>	When put on	
Coal Bunker, Openings, Lids, &c. <u>Good</u>	Caulking of	
	Bottom, Deck, & Waterways <u>Good</u>	
	Scuppers <u>Good</u>	
	Cargo and Main Hatchways <u>Good</u>	
	Hatches <u>Good</u>	

General Observations and Opinion,

She is now in an efficient state of repair and in my opinion entitled to remain as classed.

Samhouse Martindale

The Amount of Entry Fee.....£ 3 : 0 : 0 is received by me,

Special..... 2 : 2 : 0 paid in London

Certificate (if required) : 5 : 0 : 0

Committee's Minute 15th April 1873

Character assigned 90 A

J.P.W.



© 2019

Lloyd's Register Foundation