

REPORT of SURVEY for REPAIRS.

No. in
Reg. Book.

No.

Survey held at

Date, first Survey

Last Survey

18

on the

Master

Tonnage

built at

When built

By whom built

Owners

Port belonging to

Destined Voyage

If Surveyed Afloat or in Dry Dock

Last Survey, No.

Port

Classed

REPAIRS, &c.

Rudder pintles repaired, the bottom cleaned and coated with Paint and Gallon.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations and Opinion,

Treeails

Breasthooks and Stems

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shells

Ceiling

Rudder pintles repaired

Copper

When put on

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

I now in good and efficient condition, and in my opinion eligible to remain as classed.

J. H. Turner

The Amount of Entry Fee.....£

is received by me,

Special.....

Certificate (if required)

Committee's Minute

Character assigned



© 2019

Lloyd's Register
Foundation