

Damage Repairs 11358 REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 10595 Survey held at Sunderland Date, first Survey Apr 30th Last Survey May 8th 1873
535 on the Iron SS Ann Webster Master Short

Tonnage 746 built at Swansea When built 1870

By whom built Withy Owners Hill & Co

Port belonging to Sunderland Destined Voyage

If Surveyed Afloat or in Dry Dock Dry dock & part cargo in

Last Survey, No. 9800 Port Newcastle Iron Classed 90A.1.

REPAIRS, &c.

At the present time owing to damage, the middle part of stem (about lower part of keel) heated and straightened, 3 outside plates at ditto on both sides renewed with 9/16 plate. Outside bottom coated, decks part caulked. She run into Sunderland Pier.

Present Condition of the

Decks	<u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan	
Waterways		Breasthooks and Stemson <u>Good</u>	Pumps	
Comings	<u>Good</u>	Transoms, Pointers, and Crutches <u>Good</u>	Boats <u>3</u>	
Upper Deck Beams & Fastenings	<u>Good</u>	Timbers of the Frame at the openings <u>Good</u>	Masts, Yards, &c. <u>Good</u>	
Lower Deck Beams & Fastenings	<u>Good</u>	Ditto Ditto at other places <u>Good</u>	Condition, how ascertained	
Planksheers	<u>Good</u>	Keelsons <u>Good</u>	Sails	<u>Good and sufficient when they come on</u>
Sheerstrakes	<u>Good</u>	Clamps and Shelves <u>Good</u>	Anchors No. of <u>3</u>	
Topsides	<u>Good</u>	Ceiling <u>Good</u>	Cables	
Wales	<u>Good</u>	Rudder <u>Good</u>	Hawsers and Warps	
Plank (Bottom) and Counter	<u>Good</u>	Copper <u>Good</u>	Standing & Running Rigging	
Engine Room Skylights <u>Good</u>		When put on <u>Good</u>		
Coal Bunker, Openings, Lids, &c. <u>Good</u>		Caulking of <u>Good</u>		
		Bottom, Deck, & Waterways <u>Good</u>		
		Scuppers <u>Good</u>		
		Cargo and Main Hatchways <u>Good</u>		
		Hatches <u>Good</u>		

General Observations and Opinion,

She is now in an efficient state of repair and in my opinion entitled to remain as classed.

Leahouse Martindale

The Amount of Entry Fee.....£ 2 : " : " is received by me,

Special..... 1 : 1 : "

Certificate (if required) " : " : "

Committee's Minute 23rd May, 1873

Character assigned 90A.1

Damage fee £2-2-0 Good damage repair

TPW



© 2019

Lloyd's Register Foundation

IRON454-0079