

REPORT of SURVEY for REPAIRS.

11377

Rec 26/5/73

No. in Reg. Book. **No. 10601** Survey held at Sunderland Date, first Survey May 5th Last Survey May 13th 1873
 on the Iron S.S. Mllewater Master Goway
 Tonnage 764 built at Sunderland When built 1872
 By whom built Loxford Owners Strachan & Co.
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dry Dock
 Last Survey, No. 10671 Port Sunderland Classed GOA 10.72

REPAIRS, &c.

At the present time owing to damage,
 The Main Stem taken out, and straightened, and
 replaced, 3 outside Plates about the middle of the Stem
 on the Portside & 2 ditto on the Starboard side renewed
 with 8/16 plates. Outside bottom coated

Present Condition of the

Decks	Good	Treenails	Revised	Good	Windlass and Capstan	
Waterways		Breasthooks and Stemson		OK	Pumps	
Comings	OK	Transoms, Pointers, and Crutches		OK	Boats	3
Upper Deck Beams & Fastenings	OK	Timbers of the Frame at the openings		OK	Masts, Yards, &c.	Good
Lower Deck Beams & Fastenings	OK	Ditto Ditto at other places		OK	Condition, how ascertained	
Planksheers	OK	Keelsons		OK	Sails	Good and sufficient in here they could be seen
Sheerstrakes	OK	Clamps and Shells		OK	Anchors	No. of 3 Bros. & 1 Pikes
Topsides	OK	Ceiling		OK	Cables	
Wales	OK	Rudder		OK	Hawsers and Warps	
Plank (Bottom) and Counter	OK	Copper	When put on		Standing & Running Rigging	
Engine Room Skylights	Good	Caulking of			Cargo and Main Hatchways	Good
Coal Bunker, Openings, Lids, &c.	Good	Bottom, Deck, & Waterways		Good	Hatches	Good
General Observations and Opinion,	She is now in a good state of repair and in my opinion entitled to remain as classed.					

Senhouse Martindale

The Amount of Entry Fee.....£ 2 : 0 : 0 is received by me,

Special..... 2 : 2 :

Certificate (if required) : :

Committee's Minute 27th May 1873

Character assigned GOA

TPW

received damages



© 2019

Lloyd's Register Foundation