

REPORT of SURVEY for REPAIRS.

11565

Rev 27/6/73

No. in Reg. Book. 158 Survey held at London Date, first Survey April 15th Last Survey 1873

on the Iron Screw "Claine" Master _____

Tonnage 593 built at Milford When built 1864 (7 mo)

By whom built Candlish Owners Lengthened by Simsey

Port belonging to _____ Destined Voyage _____

If Surveyed Afloat or in Dry Dock Simsey's patent Slipway

Last Survey, No. 10134 Port Ton ~~Can~~ Classed 95 A 1 5.72.

REPAIRS, &c.

This Vessel now lengthened about 24 ft amidships and Classed in the Liverpool Port.

The recommendations made by the Committee as contained in the Secretary's letter dated 9th May 1873. have not been carried out.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
Engine Room Skylights	Caulking of	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	
Scuppers		
Cargo and Main Hatchways		
Hatches		

General Observations and Opinion,

I am of opinion her Character should be expunged from the Register Joseph Allen.

The Amount of Entry Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 27th June 1873

Character assigned Character Expunged



Committee's Minute 11th April, 1876

Character designed.

Insert three dots...
L. J. W. 1876
p. 11



© 2019

Lloyd's Register
Foundation