

# ANNUAL SURVEYS.

11623  
 No. 3208 Survey held at West Hartlepool Date 4th August 1873  
 on the S.S. Mary Master H. Lawson  
 Tonnage 848 Built at West Hartlepool When built 1871  
 By whom built Denton Owners Johnston & Co  
 Port belonging to Montreal Destined Voyage Baltic  
 If Surveyed Afloat or in Dry Dock In Dry Dock

Last Survey, No. 10488 Port of Iron Classed 90 A1

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>Good</u>	Breasthooks and Stenson <u>Good</u>	Pumps <u>2 or Good</u>
Comings <u>Good</u>	Transoms, Pointers, and Crutches <u>Good</u>	Boats <u>4 or Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame at the Openings <u>Good</u>	Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings <u>Good</u>	Ditto ditto at other places <u>Good</u>	Sails <u>Good</u>
Planksheers <u>Good</u>	Keelsons <u>Good</u>	Anchors, No. of <u>3 Bowers 1 S, 2 Bedges</u>
Sheerstrakes <u>Good</u>	Clamps and Shelves <u>Good</u>	Cables <u>Good</u>
Topsides <u>Good</u>	Ceiling <u>Good</u>	Hawsers and Warps <u>9-7 1/2-6 1/2-6-4 1/2-4 in Good</u>
Wales <u>Good</u>	Rudder <u>Good</u>	Standing and Running Rigging <u>Good</u>
Plank (Bottom) and Counter <u>Good</u>	Copper <u>Good</u> When put on <u>Good</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

now done. Bottom cleaned down & coated with Paint & Black varnish,

Is now in a good & efficient state fit for the safe conveyance of  
 dry perishable goods to & from all parts of the World & may in my opinion  
 remain as now classed 90 A1

Committee's Minute 12th August 1873.

Character assigned 90 A1

Certificate (if required).

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_ 18\_\_\_\_  
 on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stenson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Sails _____
Planksheers _____	Keelsons _____	Anchors, No. of _____
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing and Running Rigging _____
Plank (Bottom) and Counter _____	Copper _____ When put on _____	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18

Character assigned \_\_\_\_\_



© 2019

Lloyd's Register  
 Foundation  
 Certificate (if required).