

REPORT of SURVEY for REPAIRS.

No. in
Reg. Book.

No.

Survey held at

Date, first Survey

Last Survey

18

on the

Master

Tonnage

built at

When built

By whom built

Owners

Port belonging to

Destined Voyage

If Surveyed Afloat or in Dry Dock

Last Survey, No.

Port

Classed

REPAIRS, &c.

11747

332178

118

488

1865-4 mo

Palmer

Thieids

On the Victoria Dock's Portoon and afloat

9933

Iron

Classed

15.5.1873-72, 2-72

REPAIRS, &c.

The plate on the Port Bilge, in the waist, renewed 9th thick. Some few damaged rivets at, and around each bilge, have been taken out, and renewed. Inside cleaned, and painted throughout. Bottom scraped clean, and coated with Paint and Ballast.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations and Opinion,

Trunnels

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Stelfs

Ceiling

Rudder

Copper

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors

Cables

Hawsers and Warps

Standing & Running Rigging

Cargo and Main Hatchways

Hatches

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

The Amount of Entry Fee.....£..... is received by me,

Special.....22.....

Certificate (if required).....

Committee's Minute 22nd August 1873.

Character assigned