

# REPORT of SURVEY for REPAIRS.

17/4/73  
12114

No. in Reg. Book. No 23981 Survey held at Liverpool Date, first Survey 7<sup>th</sup> Oct<sup>r</sup> Last Survey 20<sup>th</sup> Dec<sup>r</sup> 1873  
 on the Iron S.S. Plantagenet Master Lott  
 Tonnage 726 built at London When built 1869-3mo  
 By whom built Lamuda Owners Lamuda &  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock London dry dock  
 Last Survey, No. 8344 Port Spain pt dub. bottom Classed GA1

## REPAIRS, &c.

Ceiling equal to three shakes lifted on each side in main hold - Water ballast tanks cleaned out and ceiling lifted. Cemented where necessary. Boilers taken out and a few doubtful rivets in this space renewed. Scraped and painted inside and outside.

## Present Condition of the

Decks	Good	Freecoils	Rivets	Good	Windlass and Copstan	Good
Waterways	—	Breasthooks and Stemson	—	—	Pumps	—
Comings	—	Transoms, Pointers, and Crutches	—	—	Boats	3 ho —
Upper Deck Beams & Fastenings	—	Timbers of the Frame at the openings	—	—	Masts, Yards, &c.	—
Lower Deck Beams & Fastenings	—	Ditto Ditto at other places	—	—	Condition, how ascertained	Seen from Dk
Planksheers	—	Keelsons	—	—	Sails	Good
Sheerstrakes	—	Clamps and Shelves	—	—	Anchor	No. of 3 B. 15 & 2 K
Topsides	—	Ceiling	—	—	Cables	part seen Good
Wales	—	Rudder	—	—	Hawtser and Warps	5 ho —
Plank (Bottom) and Counter	—	Copper Cement When put on	pt 1873	—	Standing & Running Rigging	—
Engine Room Skylights	—	Caulking of	—	—	Cargo and Main Hatchways	Good
Coal Bunker, Openings, Lids, &c.	—	Bottom, Deck, & Waterways	Good	—	Hatches	Good
Scuppers	Good					

## General Observations and Opinion,

She is now in good condition and in my opinion may continue as classed and marked S.S. No 1. 73

The Amount of Entry Fee.....£ - : - : - is received by me,

Special..... 3 : 3 : - 12/4/73

Certificate (if required) : 5 :

Committee's Minute Liverpool 21<sup>st</sup> November 1873

Character assigned GA1 S.S. No 1. 73

M.C. 73. Gen. 10/73.



© 2019

Lloyd's Register Foundation

IRONLSS-0462



# REPORT OF SURVEY FOR REPAIRS

Survey made on \_\_\_\_\_  
by \_\_\_\_\_  
for \_\_\_\_\_  
at \_\_\_\_\_  
on \_\_\_\_\_

Present Condition of the

Structure and Foundation  
Roofs  
Walls  
Floors  
Ceilings  
Interior  
Exterior  
Plumbing  
Electrical  
Heating  
Cooling  
Ventilation  
Sanitation  
Fire Protection  
Security  
Accessibility  
Energy Efficiency  
Historical Significance  
Other

Charita G. G. G.