

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 2** Survey held at _____ Date, first Survey **19/3** Last Survey **5/4** 18 **73**
 on the **Grand Duke Alexis** Master **Trusk**
 Tonnage **444** built at **Newcastle** When built **1871. 5 mo**
 By whom built **Mitchell** Owners **Stm Nav Co**
 Port belonging to **Archngl** Destined Voyage **4 to Norway**
 If Surveyed ~~Afloat or in Dry Dock~~ **on Land**

Last Survey, No. **1007.2** Port **from Russia** Classed **100 A**

REPAIRS, &c.

*Put in 16 plates on each side of the keel
 18 pair of frames were taken out and put
 in again. The ship was scraped and painted
 both in and outside and cemented.*

J. E. Johnson

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
Engine Room Skylights	Caulking of	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	
General Observations and Opinion,	Scuppers	Cargo and Main Hatchways
		Hatches

The Amount of Entry Fee.....£ : : is received by me,

Special..... 22 : 45

Certificate (if required) : :

Committee's Minute **24th February** 18 **74**

Character assigned **100A**