

# REPORT of SURVEY for REPAIRS.

No. in  
Reg. Book.

No.

Survey held at

Date, first Survey

Last Survey

18

on the

Master

Tonnage

built at

When built

By whom built

Owners

Port belonging to

Destined Voyage

Surveyed Afloat or in Dry Dock

Last Survey, No.

Port

Classed

REPAIRS, &c.

Placed on Blocks - A Strake of Ceiling at Bilge on each side removed. Ballast Tanks, cleared and examined, cement tried, and found good; outside surface of Plating Scraped, cleaned, and coated, with three coats of Red Lead, White Zinc Paint, and Yellow.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations and Opinion,

Vessel being in good condition and requirements of Rules complied with; is eligible in my opinion to remain as classed 90 A.S. and to have "S.S. No. 74" recorded in the Register Book.

The Amount of Entry Fee.....£

is received by me,

Special.....2 : 2 : 0

Certificate (if required) : 5 :

Committee's Minute

18

Character assigned

90 A

S.S. No. 74



Knappton Hall.

REPORT of SURVEY for REPAIRS.

24/8/6



© 2019

Lloyd's Register  
Foundation