

13059 ~~33157~~
ANNUAL SURVEYS.

Class Iron.
 99. No. 11626 Survey held at London Date 22nd July 18 74
 on the Ship "Neva" Master L. Napier
 Tonnage 1109 Built at Glasgow When built 1869 6 mo.
 By whom built Lawrie Owners Nourse & Co.
 Port belonging to London Destined Voyage Not Known
 If Surveyed Afloat or in Dry Dock London Docks & Limehouse Dry Dock.

Last Survey, No. 11626 Port of London

Classed * A
 S.S. Lon No 1-73- 633

The present Condition of the

Decks } Good
 Waterways }
 Comings }
 Upper Deck Beams & Fastenings } Form
 Lower Deck Beams & Fastenings }
 Planksheers }
 Sheerstrakes } Good
 Topsides }
 Wales }
 Plank (Bottom) and Counter }

~~Transoms~~ Rivets.
~~Breasthooks and Stemson~~
~~Transoms, Pointers, and Crutches~~
 Timbers of the Frame at the Openings } Good
 Ditto ditto at other places }
 Keelsons }
~~Clamps and Shells~~
 Ceiling }
 Rudder }
~~Copper~~ Paint When put on Now

Windlass and Capstan Good
 Pumps 2 M. 2 B. do.
 Boats 6 (2 as life) do.
 Masts, Yards, &c. do.
 Sails double suit do.
 Anchors, No. of 3 B-1 S-2 K do.
 Cables part seen do.
 Hawsers and Warps } good &
 Standing and Running Rigging } sufficient.

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good.

Bottom now painted with 2 coats of fine & one coat of Tallow.
She is now in a good & efficient condition, eligible in my
opinion to remain as classed.

Committee's Minute 31st July 18 74

J. Shilston

Character assigned 1

Certificate (if required).

77. No. 11401 Survey held at London Date July 20th 18 74
 on the Ship "Lady Lawrence" Master
 Tonnage 1407 Built at Liverpool When built 1868 8 mo.
 By whom built J. Royden & Son Owners Farnworth & Jardine.
 Port belonging to Liverpool Destined Voyage Not Known
 If Surveyed Afloat or in Dry Dock Canal Dry Dock.

Last Survey, No. 11401 Port of London

Classed * All
 S.S. Lon No 1-73- 573

The present Condition of the

Decks } Good
 Waterways }
 Comings }
 Upper Deck Beams & Fastenings } Good
 Lower Deck Beams & Fastenings }
 Planksheers }
 Sheerstrakes } Good
 Topsides }
 Wales }
 Plank (Bottom) and Counter }

~~Transoms~~
~~Breasthooks and Stemson~~
~~Transoms, Pointers, and Crutches~~
 Timbers of the Frame at the Openings } Good
 Ditto ditto at other places }
 Keelsons }
~~Clamps and Shells~~
 Ceiling }
 Rudder }
~~Copper~~ Paint When put on Now

Windlass and Capstan Good
 Pumps 2 M. 2 B. do.
 Boats 4 (2 as life) do.
 Masts, Yards, &c. do.
 Sails double suit do.
 Anchors, No. of 3 B-1 S-2 K do.
 Cables part seen do.
 Hawsers and Warps } good &
 Standing and Running Rigging } sufficient

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good.

Bottom now painted with two coats of MacIntosh's paint, rudder hangings
brushed. She is now in a good and efficient condition, eligible
in my opinion to remain as classed * All.

Committee's Minute 31st July 18 74

J. Shilston

Character assigned 1

Certificate (if required).