

13075 ~~33775~~
ANNUAL SURVEYS.

~~33825~~
~~34025~~

Recd 4.8.74
[Signature]

No. 1340 Survey held at London Date July 30th 1874
 on the Sun Screw Steamer America Master R. Stevens
 Tonnage 873 Built at Dumbarton When built 1872
 By whom built Swan Owners Munro & Co.
 Port belonging to Glasgow Destined Voyage Sevill
 If Surveyed Afloat or in Dry Dock Commercial dry dock

Last Survey, No. 11053 Port of Brown Classed 90. A. 1.

The present Condition of the

Decks	good	Freemasts	Rivets where seen	good	Windlass and Capstan	in good order
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Sails	"
Planksheers	"	Keelsons	"	"	Anchors, No. of <u>3 B. 1 S. 2 K</u>	"
Sheerstrakes	"	Clamps and Shelves	"	"	Cables	"
Topsides	"	Ceiling	"	"	Hawsers and Warps	"
Wales	"	Rudder <u>efficient</u>	"	"	Standing and Running Rigging	"
Plank (Bottom) and Counter	"	Copper	When put on	"		

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good

Cleaned and recaused the bottom. She is in good and efficient condition and in my opinion is entitled to remain as class'd 90. A. 1.

Committee's Minute 11th August 1874 Samuel Presious

Character assigned 90 A IRW

Certificate (if required).

No. 1340 Survey held at London Date 28th July 31st 1874
 on the Sun Screw Steamer Woodham Master W^m Clark
 Tonnage 1024 Built at Hartlepool When built 1869
 By whom built Newson Owners Pembrose & Co.
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock mile wall dry dock &

Last Survey, No. 12573 Port of Brown Classed 90. A. 1. S.S. 203/74

The present Condition of the

Decks	good	Freemasts	Rivets where seen	good	Windlass and Capstan	in good order
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Sails	"
Planksheers	"	Keelsons	"	"	Anchors, No. of <u>3 B. 1 S. 2 K</u>	"
Sheerstrakes	"	Clamps and Shelves	"	"	Cables	"
Topsides	"	Ceiling	"	"	Hawsers and Warps	"
Wales	"	Rudder <u>efficient</u>	"	"	Standing and Running Rigging	"
Plank (Bottom) and Counter	"	Copper	When put on	"		

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good

Repairs chiefly from damage by grounding, 'See Report of Survey'
Fitted a new iron bearer or bracket to outer end of propeller. - Cleaned and recaused the bottom.
and Caulked the Deck. She is now in good condition, and entitled to remain as class'd 90. A. 1.

Committee's Minute 11th August 1874 Samuel Presious

Character assigned 90 A IRW

Certificate (if required).

Amesbury
Woodham



© 2019

Lloyd's Register
Foundation