

ANNUAL SURVEYS.

No. in Reg. Book. **189** No. **13479** Survey held at **London** Date, first Survey **Oct 5** Last Survey **1874**
 on the **Iron S. Jane Porter** Master **W. Leg**
 Tonnage **953** Built at **Belfast** When built **1860** & M.
 By whom built **Harland** Owners **Corry & Sons**
 Port belonging to **Belfast** Destined Voyage **Calcutta**
 If Surveyed Afloat or in Dry Dock **Dry Dock**

Last Survey, No. **11089** Port of **Iron** Classed **A1** Years assigned **2-73** Character in Register Book **68 Dec. No 3-73**
 Present Condition of the
 Decks **Good** Treennails **Rivets** **Good**
 Waterways **do** Breasthooks and Stenson **do**
 Comings **do** Transoms, Pointers, and Crutches **do**
 Upper Deck Beams & Fastenings **do** Timbers of the Frame at the Openings **do**
 Lower Deck Beams & Fastenings **do** Ditto ditto at other places **do**
 Planksheers **Plating** **do** Keelsons **do**
 Sheerstrakes **do** **do** Clamps and Shelves **do**
 Topsides **do** **do** Ceiling **do**
 Wales **do** **do** Rudder **do**
 Plank (Bottom) and Counter **do** **do** Copper or Y.M. **do** When put on **do**
 Caulking of Bottom, Deck, & Waterways **Good**
 Engine Room Skylights **do** Coal Bunker, Openings, Lids, &c. **do** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c.

*at the present time the bottom scraped painted & brated
 she is now in an efficient state of repair and
 in my opinion entitled to remain as classed*

Committee's Minute **16th October** 18 **74** **Senhouse Martin**
 Character assigned **A1** **J.B.W.** Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **do** Paid **do** 18 **do**

No. in Reg. Book. **74** No. **13479** Survey held at **London** Date, first Survey **Sept 28th** Last Survey **1874**
 on the **Iron SS Baron Selborne** Master **Lamplough**
 Tonnage **608** Built at **Sunderland** When built **1872** 12 mo.
 By whom built **Wm Watson** Owners **J Mac Gunn**
 Port belonging to **Greenock** Destined Voyage **no fixed**
 If Surveyed Afloat or in Dry Dock **Pontoon**

Last Survey, No. **12465** Port of **Iron** Classed **90A1** Years assigned **3-74** Character in Register Book **do**
 Present Condition of the
 Decks **Good** Treennails **Rivets** **Good**
 Waterways **do** Breasthooks and Stenson **do**
 Comings **do** Transoms, Pointers, and Crutches **do**
 Upper Deck Beams & Fastenings **do** Timbers of the Frame at the Openings **do**
 Lower Deck Beams & Fastenings **do** Ditto ditto at other places **do**
 Planksheers **Plating** **do** Keelsons **do**
 Sheerstrakes **do** **do** Clamps and Shelves **do**
 Topsides **do** **do** Ceiling **do**
 Wales **do** **do** Rudder **do**
 Plank (Bottom) and Counter **do** **do** Copper or Y.M. **do** When put on **do**
 Caulking of Bottom, Deck, & Waterways **Good**
 Engine Room Skylights **do** Coal Bunkers, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c.

*at the present time the bottom scraped painted & brated
 she is now in an efficient state of repair and
 in my opinion entitled to remain as classed*

Committee's Minute **16th October** 18 **74** **Senhouse Martin**
 Character assigned **90A1** **J.B.W.** Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **do** Paid **do** 18 **do**