

ANNUAL SURVEYS.

14719
321-810

No. 319 Survey held at London Date June 28th 1875
 on the SS Italia Master Shaker
 Tonnage 584 Built at Greenock When built 1868 5 M
 By whom built Scott Owners Sen & Ship Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Pontoon

Last Survey, No. 13048 Port of Iron Classed A1 8.74
SS Sen No 1-73

The present Condition of the

Decks	<u>Good</u>	Timbers	<u>Rivet</u>	<u>Good</u>	Windlass and Capstan	
Waterways	"	Breasthooks and Stemson		"	Pumps	
Comings	"	Transoms, Pointers, and Crutches		"	Boats	
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings		"	Masts, Yards, &c.	<u>Good</u>
Lower Deck Beams & Fastenings	"	Ditto ditto at other places		"	Sails	<u>and</u>
Planksheers	"	Keelsons		"	Anchors, No. of <u>3 Sen & Ship Co</u>	<u>Sufficient</u>
Sheerstrakes	"	Clamps and Shelves		"	Cables	<u>where they</u>
Topsides	"	Ceiling		"	Hawsers and Warps	<u>could be</u>
Wales	"	Rudder		"	Standing and Running Rigging	<u>seen</u>
Plank (Bottom) and Counter	"	Copper <u>Painted</u> When put on <u>now</u>				

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

*at present the bottom scraped Painted & coated
 She is now in an efficient state of repair
 and entitled to remain as classed*

Committee's Minute 13th July 18 75

Character assigned B

Senhouse Martindale
JRW

Certificate (if required).

No. 852 Survey held at London Date June 7th 1875
 on the SS Medora Master _____
 Tonnage 512 Built at Newcastle When built 1864 5 mo.
 By whom built Palmer Owners London & Ship Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Pontoon

Last Survey, No. 12801 Port of Iron Classed 80 A1 5.74
SS Sen No 76

The present Condition of the

Decks	<u>Good</u>	Timbers	<u>Rivet</u>	<u>Good</u>	Windlass and Capstan	
Waterways	"	Breasthooks and Stemson		"	Pumps	
Comings	"	Transoms, Pointers, and Crutches		"	Boats	
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings		"	Masts, Yards, &c.	<u>Good</u>
Lower Deck Beams & Fastenings	"	Ditto ditto at other places		"	Sails	<u>and</u>
Planksheers	"	Keelsons		"	Anchors, No. of <u>3 Sen & Ship Co</u>	<u>Sufficient</u>
Sheerstrakes	"	Clamps and Shelves		"	Cables	<u>where</u>
Topsides	"	Ceiling		"	Hawsers and Warps	<u>they could</u>
Wales	"	Rudder		"	Standing and Running Rigging	<u>be seen</u>
Plank (Bottom) and Counter	"	Copper <u>Painted</u> When put on <u>now</u>				

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

*at present the bottom scraped Painted & coated
 She is now in an efficient state of repair
 and entitled to remain as classed*

Committee's Minute 13th July 18 75

Character assigned 80 A1

Senhouse Martindale
JRW

Certificate (if required).