

ANNUAL SURVEYS.

No. 544 Survey held at London Date Recd 9.7.75
July 2^d 1875
 on the SS Prostoff Master _____
 Tonnage 816 Built at Newcastle When built 1867 SM
 By whom built Mitchell Owners Russian S. N 2 Lady &c
 Port belonging to Odesa Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Pontoon

Last Survey, No. 13532 Port of Iron Classed A1 8.73
SS Ben M 2-73

The present Condition of the

Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan	
Waterways	"	Breasthooks and Stemson	"	Pumps	
Comings	"	Transoms, Pointers, and Crutches	"	Boats	
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Masts, Yards, &c.	<u>Good</u>
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	Sails	<u>and</u>
Planksheers	"	Keelsons	"	Anchors, No. of <u>3 No. 8 & 10</u>	<u>Sufficient</u>
Sheerstrakes	"	Clamps and Shelves	"	Cables	<u>where</u>
Topsides	"	Ceiling	"	Hawsers and Warps	<u>they could</u>
Wales	"	Rudder	"	Standing and Running Rigging	<u>be seen</u>
Plank (Bottom) and Counter	"	Copper	<u>Painted</u> When put on <u>Now</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

At present the bottom scraped painted & coated
She is now in an efficient state of repair
and entitled to remain as classed

Committee's Minute 13th July 18 75 Senhouse Martindale

Character assigned B1 T.D.W.

Certificate (if required).

No. 340 Survey held at London Date June 16th 1875
 on the S Jessie Readman Master Muir
 Tonnage 1263 Built at Greenock When built 1869 HM
 By whom built Scott Owners Albion Ship Co
 Port belonging to Glasgow Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 13094 Port of Iron Classed *A1 7.74
P.S. No. 1. 74

The present Condition of the

Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan	
Waterways	"	Breasthooks and Stemson	"	Pumps	
Comings	"	Transoms, Pointers, and Crutches	"	Boats	
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Masts, Yards, &c.	<u>Good</u>
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	Sails	<u>and</u>
Planksheers	"	Keelsons	"	Anchors, No. of <u>3 No. 8 & 10</u>	<u>Sufficient</u>
Sheerstrakes	"	Clamps and Shelves	"	Cables	<u>where they</u>
Topsides	"	Ceiling	"	Hawsers and Warps	<u>could be</u>
Wales	"	Rudder	"	Standing and Running Rigging	<u>seen</u>
Plank (Bottom) and Counter	"	Copper	<u>Painted</u> When put on <u>Now</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

At present the bottom scraped painted & coated
She is now in an efficient state of repair
and entitled to remain as classed

Committee's Minute 13th July 18 75 Senhouse Martindale

Character assigned B1 T.D.W.

Certificate (if required).