

ANNUAL SURVEYS.

No. in Reg. Book. **94** No. **1488** Survey held at **London** Date, first Survey **1875** Last Survey **1875**
 on the **S Indian Empire** Master **Watson**
 Tonnage **1515** Built at **W Hartlepool** When built **1865** 7M
 By whom built **Pile** Owners **G Duncan**
 Port belonging to **London** Destined Voyage
 If Surveyed Afloat or in Dry Dock **Dry Dock**

Last Survey, No. **13413** Port of **London** Classed **A1** Years assigned **10.74** Character in Register Book
 Present Condition of the
 Decks **Good** Treennails **Pivots** **Good**
 Waterways **"** Breasthooks and Stemson **"**
 Comings **"** Transoms, Pointers, and Crutches **"**
 Upper Deck Beams & Fastenings **"** Timbers of the Frame at the Openings **"**
 Lower Deck Beams & Fastenings **"** Ditto ditto at other places **"**
 Planksheers **"** Keelsons **"**
 Sheerstrakes **"** Clamps and Shelves **"**
 Topsides **"** Ceiling **"**
 Wales **"** Rudder **"**
 Plank (Bottom) and Counter **"** Copper or Y.M. **Painted** When put on **Now**
 Caulking of Bottom, Deck, & Waterways **Good**
 Engine Room Skylights **"** Coal Bunker, Openings, Lids, &c. **"** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c.

She is now in an efficient state of repair and entitled to remain as classed Bottom Scraped Painted & Coated

Senhouse Martindale

Committee's Minute **20th August 1875**

Character assigned **A1**

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. in Reg. Book. **33** No. **1445** Survey held at **London** Date, first Survey **1875** Last Survey **July 22 1875**
 on the **SS Odesa** Master **Ruspan St Mac**
 Tonnage **1445** Built at **Waterford** When built **1857**
 By whom built **"** Owners **Ruspan St Mac**
 Port belonging to **Odesa** Destined Voyage
 If Surveyed Afloat or in Dry Dock **Dry Dock**

Last Survey, No. **13510** Port of **London** Classed **85A** Years assigned **10.72** Character in Register Book
 Present Condition of the
 Decks **Good** Treennails **Pivots** **Good**
 Waterways **"** Breasthooks and Stemson **"**
 Comings **"** Transoms, Pointers, and Crutches **"**
 Upper Deck Beams & Fastenings **"** Timbers of the Frame at the Openings **"**
 Lower Deck Beams & Fastenings **"** Ditto ditto at other places **"**
 Planksheers **"** Keelsons **"**
 Sheerstrakes **"** Clamps and Shelves **"**
 Topsides **"** Ceiling **"**
 Wales **"** Rudder **"**
 Plank (Bottom) and Counter **"** Copper or Y.M. **Painted** When put on **Now**
 Caulking of Bottom, Deck, & Waterways **Good**
 Engine Room Skylights **Good** Coal Bunkers, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c.

She is now in an efficient state of repair and entitled to remain as classed

Senhouse Martindale

Committee's Minute **20th August 1875**

Character assigned **85A**

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18