

15869

REPORT of SURVEY for REPAIRS.

Rev 24/2/76

No. in Reg. Book. **No. 132** Survey held at Bergen Date, first Survey _____ Last Survey Nov 11th 1870
 on the SS Aurora Master H Ingelsen
 Tonnage 1231 built at Bergen When built 1874 - 10mo
 By whom built Bergen Mek Værsted Owners E Håns
 Port belonging to Bergen Destined Voyage over Sea
 If Surveyed Afloat or in Dry Dock Surveyed in Dry dock

Last Survey, No. # 13957 Port Bergen Classed 90 A 1
 REPAIRS, &c. Span decked 2.35

Surveyed the paint of the bottom and the fastening of the propeller having been requested to do so by the owner

Present Condition of the		
Decks <u>good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
Engine Room Skylights	Caulking of	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	
Scuppers		Cargo and Main Hatchways
Hatches		

General Observations and Opinion, Specimen

The Amount of Entry Fee.....£ : : is received by me,
 Special..... / : :
 Certificate (if required) : :

Committee's Minute 25th February 1876

Character assigned 90 A 1
JRM

J.P. Johnson
 Survey to Lloyd's Register



Lloyd's Register Foundation

IRON465 - 0151