

J. J. "Shoeborn"

It is respectfully submitted
that Mr Reed should be requested
to explain more fully the meaning
of "defective" floors and angles.
As it is important to ascertain
the cause of such an extensive repair
as this, it is submitted that it
should be stated whether the vessel
had been on shore, or whether she
grounded during loading; and
to state fully for the information
of the Committee, what in ^{Mr Reed's} ~~his~~
opinion, occasioned the necessity
of the removal of floor plates &c
and the ~~for~~ large repairs described

JJR
24/11/76



© 2019

Lloyd's Register
Foundation

1R0N469 - 0432