

1897

364/20
Recd 21.7.77

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. 686 No. 18045 Survey held at London Date, first Survey 9th July Last Survey 24th July 1877
 on the S.S. "Emperor" Master Leighton
 Tonnage 1120 built at Glasgow When built 1849
 By whom built Napier Owners Liddell
 Port belonging to Hull Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Regent dock and afloat. Internally Dock
 Last Survey, No. 18045 Port London Classed 85 A1 6.75
 S.S. No. 75

REPAIRS, OR EXAMINATION AS PER RULE

One plate renewed, on account of damage, in the third strake from funnel gunships on the R. side.

See previous report March 77

Cause of Repairs to be clearly stated.

Present Condition of the

Decks) <u>Good</u>	Treenails) <u>Good</u>	Windlass and Capstan) <u>Good</u>
Waterways		Breasthooks and Stenson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper When put on		Standing & Running Rigging	
Engine Room Skylights	Caulking of				
	Bottom, Deck, & Waterways				
	Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo and Main Hatchways	Hatches	

General Observations, Opinion as to Class &c. This vessel appears in good condition and eligible to remain as classed.

The Amount of Entry Fee £ " : " : " received by me,
 1/8/77 Special £ 1 : 4 August 1877
 Certificate (if required) £ : :
 (Travelling Expenses, if any, £ _____)

Committee's Minute 7th August, 1877

Character assigned 85 A1

[Handwritten signature: J. H. Congdon]
 Surveyor to Lloyd's Register of British and Foreign Shipping.

 © 2019 Lloyd's Register Foundation