

ANNUAL SURVEYS.

No. in Reg. Book. **849** No. **4576** Survey held at **Hull** Date, first Survey **17th July** Last Survey **5th August** **1877**
 on the **Iron Steamer "Anglo Norman"** Master **A Davidson**
 Tonnage **822** Built at **P Glasgow** When built **1876** 1st No.
 By whom built **Russell** Owners **Frost & Co**
 Port belonging to **London** Destined Voyage **Sydney**
 If Surveyed Afloat or in Dry Dock **In proportion glassy Dock Afloat in Humber Dock**

Last Survey, No. **15863** Port of **Iron**

Classed

Years assigned.

Character in Register Book.

100 A 1

3.76

Present Condition of the Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Now done The close ceiling lifted Cement Renewed Ceiling replaced Is eligible in our opinion to remain as classed 100 A 1

Committee's Minute

14th September

1877

Character assigned

100 A 1

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18

No. in Reg. Book. **1167** No. **—** Survey held at **Hull** Date, first Survey **17th May** Last Survey **8th Sept** **1877**
 on the **Iron Steamer "Sultan"** Master **Barron**
 Tonnage **666*** Built at **Hull** When built **1867** 4th No.
 By whom built **1025 Earle** Owners **W Siddell**
 Port belonging to **Hull** Destined Voyage **Hamburg**
 If Surveyed Afloat or in Dry Dock **On N-2 slip-way & afloat in Humber & Princes Dock**

Last Survey, No. **16540** Port of **Iron**

Classed

Years assigned.

Character in Register Book.

90 A 1

6-76

Present Condition of the Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunkers, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Bottom cleaned & painted Windlass repaired Is eligible in my opinion to remain as classed 90 A 1

Committee's Minute

14th September

1877

Character assigned

90 A 1

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18