

# ANNUAL SURVEYS.

Rev 3/2/77

No. 451 Survey held at Glasgow Date 1st & 2nd Sept 1877  
 184 on the Ship Canterbury Master Leslie  
 Tonnage 1345 Built at Port Glasgow When built 10th 5 mo.  
 By whom built R. Duncan & Co Owners Colind Shipping Co  
 Port belonging to Glasgow Destined Voyage By  
 If Surveyed Afloat or in Dry Dock Reh. of Henderson's painting dock and Afloat

Last Survey, No. 14095 Port of GlasgowClassed 100A

10.76

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>Not seen</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>Good</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	Sails <u>Said to be complete</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Anchors, No. of <u>3 B. 18. 24</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Cables <u>Said to be complete</u>
Topsides <u>"</u>	Ceiling <u>Good</u>	Hawsers and Warps <u>Good</u>
Wales <u>"</u>	Rudder <u>"</u>	Standing and Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper <u>Coin 74</u> When put on <u>"</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

The bottom recoated. She is in good and efficient condition eligible to remain as classed 100A

Committee's Minute 5th October, 18 77Char acter assigned 100A

Certificate (if required).