

20728.

Report of Survey for Repairs of Engines and Boilers.

No. _____
No. in Reg. Book: Survey held at London Date, first Survey _____ Last Survey 18
333 on the Screw Steamer "Henry Morton" Master _____
Tons 486 Owners J. Hurcklen Port belonging to London Classified _____ Years assigned _____ Character in Register Book. A1

Diameter of Cylinder 26 1/2 Engines made at London When made 1844
Length of Stroke 30 By whom made Viet Dock Eng Works Co.
Pressure of Steam 75
Registered Horse Power 99

Particulars of Repairs and Examination, At request of Mr. Fenwick
Examined Low pressure Steam chest, found it cracked
round exhaust pipe, the crack extending to the
lower steam port. This has been repaired by
means of 2 Cast Iron patches securely bolted on,
making a good job of it. Other parts of machinery
not examined

The Amount of Fee ... 6/4 ... £ 1 : 1 : 0 received by me, J. M. Hullon
Certificate (if required) ... £ : : 24 April 1878
Travelling Expenses, if any, £ _____
Committee's Minute 5th April 1878
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Machine, it has since been
repaired under the inspection
of the Society's Surgeon
submitted that she is
eligible to remain as
Classed

MD 5-4-78



© 2019

Lloyd's Register
Foundation