

Report of Survey for Repairs of Engines and Boilers.

No. 57

No. in Reg. Book. Survey held at

425 on the

Tons 630
395

Owners

Diameter of Cylinders

Length of Stroke

Pressure of Steam

Registered Horse Power

Particulars of Repairs and Examination

Boiler taken out of the ship for repairs. Both furnaces and backplate cut out of the boiler. Tops of furnaces, lower part of frontplate, lower part of endplate and lower part of backplate of combustion chamber renewed. 52 new screw stays 1 1/4" dia put in. In my opinion can remain as closed.

Date, first Survey

Last Survey

Master

Classed

Years assigned

Character in Register Book

When made

Engines made at

By whom made

The Amount of Fee

Certificate (if required)

Travelling Expenses, if any, £

Committee's Minute

received by me,

1878

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

© 2019

Lloyd's Register

IRON 477-0504

1/18/76.

The Maching of this vessel has been -
repaired and is reported to be in good -
condition submitted that she is
eligible to remain as cleared

MP 13.5.72



© 2019

Lloyd's Register
Foundation