

Report of Survey for Repairs of Engines and Boilers.

* 22666

(Rec. 3/2/79)

No. in Reg. Book. *127* Survey held at *South Shields* Date, first Survey *23rd* and Last Survey *27th January 1879*
8 on the *Iron S.S. "Benarain"* Master *L. Talbot*
 Built at *Aberdeen* When built *1878-5 mo.*
 Tons *274* Owners *J. & A. Davidson* Port belonging to *Aberdeen* Classified *100 A 1*
381 *5.78*
308

Diameter of Cylinder *19" & 30 3/4"* Engines made at *Aberdeen* When made *1878*
 Length of Stroke *22"*
 Pressure of Steam *62 lb.*
 Registered Horse Power *43* By whom made *Messrs Hall Russell & Co.*

Particulars of Repairs and Examination

The Machinery of this vessel was examined on the 23rd Inst. the vessel being in Messrs Edwards & Sons Dry Dock South Shields, to ascertain the damage reported to have been done by the end of the propeller shaft dropping off at sea on the morning of the 21st Inst. and carrying the propeller along with it. See damage report of the 27th Inst.
 No other damage was apparently done to the Machinery or Boiler.

A new end was welded on to the Stern shaft, a new aft brass liner was fitted on the shaft, and the shaft fitted to a new propeller.

The Machinery of this vessel is now in good order and safe working condition, and eligible in my opinion to retain her class in the Society's Register Book.

The Amount of Fee ... £ 2 : 2 : received by me,

Certificate (if required) ... £ - : - : 1st Feb 1879

(Travelling Expenses, if any, £)

Committee's Minute

18

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

North Shields

Lloyd's Register Foundation

IRON 482-0368

Working of this vessel has been
examined and is reported to be
in good condition submitted
that she is eligible to remain
as classed

MD

4.1.79

TBW



© 2019
Lloyd's Register
Foundation