

# REPORT of SURVEY for REPAIRS, &c.

22745 37.8724

No.

No. in  
Reg. Book.

Survey held at

Date, first Survey

Last Survey

Master

YEAR.

MONTH.

TONNAGE under Tonnage Deck

Ditto of Spar Deck, or Awning Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St mer, cut on Bm.

Built at

When built

Owners

Port belonging to

Residence

By whom built

Destined Voyage

If Surveyed Afloat or in Dry Dock

Length of Poop

ft.

Ditto, Forecastle

ft.

Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Last Survey, No.

Port

Classed

REPAIRS, OR EXAMINATION AS PER RULE

At present owing to damage and defect  
Renewed a good deal of the Ribs and Moulding  
Mast head caps lower down and refitted the Devel  
rig changed into a Barque.  
New Mizzen Mast & Mizzen Top Mast and Bowsprit  
of Wood.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Bottom scraped & coated

She is now in good condition  
and entitled to remain as classed.

Damage just 3-3-0

The Amount of Entry Fee ... £ ... received by me,

30/1/79 Special ... £ ... 21/6/1879

Certificate (if required) ... £ ...

(Travelling Expenses, if any, £ ...)

Committee's Minute

31st January,

1879.

Character assigned

Senhouse Martindale

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register  
Foundation

IRON482-0466