

doors on after Bulkhead; Repaired Cement in place
 Caulked a few butts of Bottom at the Bilges;
 payed the Bottom with patent Composition and
 from thence upwards also internally throughout,
 the iron work painted, the Tank tops tarred and
 Cemented.

The following Anchors have renewed, and have retested.

	cut or lbs	Tested to	Don. cut or lbs		
Bones ex Stock	12.1.18	tested to	14.16.1.0	at R. N. C. P. by J. Hastings May	
" " "	12.0.0	" "	13.17.2.0	Do	Do "
" " "	10 0 0	" "	12.0.0.0	Do	Do "
Streamers incl ^{ing} "	5.0.0	" "	6.7.2.0	Do	Do July
Kedges " "	2.2.14	" "	4.7.0.21	Do	Do May 3.
" " "	1.1.10				

The Ships Register was submitted for inspection
 but there was no deductions recorded for Crew Space
 the men however live under the Foreage Deck and
 is estimated that they occupy a space equal to ^{about} 30%
 which brings the equipment on the 45 tons & scale.

Joseph Allen.
 Lieutenant



© 2019

Lloyd's Register
Foundation