

ANNUAL SURVEYS.

No. 23896 Survey held at London Date, first Survey May 23 Last Survey June 27 1879
 No. in on the BR Lizzie Bell Master Moigard
 Reg. Book 546 Tonnage 1036 Built at Sunderland When built 1877 - 11/11
 By whom built Thompson Junr Owners P Fudale
 Port belonging to Liverpool Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Blackwall Point by St
 Last Survey, No. 20049 Port of Iron Classed 100A1 1.78

Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. Coated When put on Now
 Caulking of _____
 Bottom, Deck, & Waterways Good
 Engine Room Skylights _____ Coal Bunker, Openings, Lids, &c. _____ Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom Coated.

*She is now in good condition
and entitled to remain as classed.*

Committee's Minute 1st July, 18 79. Senhouse Martindale
 Character assigned 100A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. 23896 Survey held at London Date, first Survey May 23 Last Survey June 14 1879
 No. in on the S Ashmore Master S Simpson
 Reg. Book 1330 Tonnage 1099 Built at Glasgow When built 1877 - 3/11
 By whom built Reid Owners J Stewart & Co.
 Port belonging to London Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock Johnson's Wharf by St
 Last Survey, No. 21034 Port of Iron Classed 100A1 6.78

Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. Coated When put on Now
 Caulking of _____
 Bottom, Deck, & Waterways Good
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom Coated.

*She is now in good condition
and entitled to remain as classed.*

Committee's Minute 1st July, 18 79. Senhouse Martindale
 Character assigned 100A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____