

25846 Even
Report of Survey for Repairs of Engines and Boilers.

No. _____ (Received at London Office, 16 . 3 . 80)
No. in Reg. Book. Survey held at London. Date, first Survey _____ and Last Survey Mar: 15th 1880
on the Machinery of the S. S. "Berrington" (Number of Visits 1)
Tonnage, Gross 794 Built at Newcastle When built 1865
Ditto, Net 508 Owners J. Finwick & Son Port belonging to Sunderland.
Diameter of Cylinder 25" x 48" Engines made by Palmers Co. When made Comp. 1876.
Length of Stroke 30" Boilers made by Palmers Co. When made 1876
Pressure of Steam 75 lbs. If Surveyed Afloat or in Dry Dock Dry Dock Years assigned. Character in Register Book.
Registered Horse Power 99 Classified 80A1
Last Survey No. _____ Port _____ Lloyd's M.C. 4.79.

Particulars of Repairs and Examination Examined sea connections, found one bolt slack in donkey suction, recommended joint to be remade, which has been done. New propeller fitted.

General Observations, Opinion, and Recommendation:— In my opinion this ship is eligible to remain as classed.


Entry or Registering Fee 24/3/80 £ : :
Survey Fee ... £ 1 : 1 : 0 received by me, Geo. E. Merriamson.
Certificate (if required) ... £ : : 24.3. 1880

(Travelling Expenses, if any, £ _____)

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute Thursday, March, 25th 1880

Assigned _____



Lloyd's Register
Foundation

IRON490-0487

It is submitted that
this vessel is eligible
to remain a classed

RM

16/3/80



© 2019

Lloyd's Register
Foundation