

Mewar

REPORT OF SURVEY FOR REPAIRS OF ENGINES AND BOILERS.

(Rev. 06/06/80)

No. 225-

Survey held at Union Dock, Howrah Date, first Survey 25th May Last Survey 26th May 1880
 Reg. Book No. 15

1	on the	s.s. <u>Maharani</u>	Master	J. Carson
Built at	<u>Belfast</u>	When built	<u>1879</u>	Years assigned.
Tons	<u>1047</u>	Owners	<u>Asiatic Steam Navigation Co. Ltd</u>	Character in Register Book
				<u>100-A1</u>
Port belonging to <u>Liverpool</u>				

Diameter of Cylinder _____ YEAR. _____
 Length of Stroke _____ Engines made at _____ When made _____
 Pressure of Steam 10 lbs
 Registered Horse Power 190 HP By whom made 62. Rowan

Particulars of Repairs and Examination of s.s. Maharani
Propeller Shaft. Examined the stern pipe bush, while the vessel was in the dock, which was found to be $\frac{3}{8}$ " of an inch worn down, propeller was removed and shaft drawn, new Lignum Vitae staves were replaced and securely fitted, the brass lining or covering which extends the whole length of this shaft, was in excellent condition

Recent Repairs and Examinations, to be clearly stated.)

S.S.

Edition of Eng.

M. Stewart
Surgeon

The Amount of Fee ... £ : : received by me, }
 Certificate (if required) ... £ : : 187 }
 Travelling Expenses, if any, £ _____

Committee's Minute _____ 18 _____

I. Hartshorn

Marine Engineer.

© 2019



H.L. 493-0277
Hodgson's Register
Foundation

The. Stern hib shaft 80.
Propeller of this vessel has been
examined and reported and is
now inscribed to be in
good condition. Submitted
that she is eligible to
remain as classed.

M

25-6-80

