

Report of Survey for Repairs of Engines and Boilers.

28286

(Received at London Office, 15. 11. 80)

No. 39802
 No. in Reg. Book. 656 Survey held at London Date, first Survey 4 Last Survey Nov 12 1880
 on the Machinery of the SS "London" (Number of Visits two)

Tonnage, Gross 1325 Built at Newcastle When built 1862
 Ditto, Net 831 Owners J. Hall & Co Port belonging to London
 Diameter of Cylinder 43 Engines made by R & W Hawthorn When made 1862
 Length of Stroke 33 Boilers made by _____ When made _____
 Pressure of Steam 40 Surveyed Afloat in Dry Dock
 Registered Horse Power 120 Classified _____ Years assigned _____ Character in Register Book. 100A1
 Last Survey No. _____ Port _____ P. S. No. 3-73 7.79
S. S. No. 1-73

Particulars of Repairs and Examination New half crankshaft fitted in place of the half shaft found to be flawed.

General Observations, Opinion, and Recommendation:— This shaft is now in my opinion in good order, and the vessel, as far as the machinery is concerned, eligible to retain her class.

Entry or Registering Fee ... £ : :
 Survey Fee ... £ : : — received by me,
 Certificate (if required) ... £ : : — 188 }
 (Travelling Expenses, if any, £)

James J. Milton
 Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute Tuesday, November, 16th 1880.

Assigned

J. W. Proctor



© 2019
 Lloyd's Register
 Foundation

Insert Character precisely as in the Register Book.

The Surveyors are requested not to write on the back of this Report.