


Are the scantlings  
or frames of the  
" Viceroy St "  
large enough for her  
increased Tonnage


21/1/70

The Surveyors are requested to report  
on the above enquiry of Mr. Mills

Taking into consideration the closer span  
of Frames than is required <sup>is</sup> Reg 10 Division of  
21<sup>ins</sup>, and the extra longitudinal Strake  
of Spunkitting, and ~~double~~ Angle on Stringers  
there will be found ample compensation  
for the slight deficiency in scantling of  
Frames, and slight excess of Tonnage by  
Rule under T. Dick

21/1/70

 J. B. C.



© 2021

Lloyd's Register  
Foundation

IRONS02-0107