

This is very satisfactory and appears to have been attended to before the telegram was sent.

From the report the crack in the jacketing of the Low pressure slide casing appears to be of the same nature as that recently surveyed by Mr Allison and myself in the S.S. "St. Osyth" and the recommendation appears to be the same.

MP 9/6/75



© 2021

Lloyd's Register
Foundation