

SURVEYOR'S REMARKS.

Timbering.

The Quality,
Squaring, and
Workmanship.

As far as it can be seen which is to a limited extent, it appears to be of good quality well squared & wrought.

Planking.

Outside and Inside
Quality, Edging,
and Workmanship.

Outside aloft of good quality well edged and wrought.
Ceiling Painted Oak of good quality well edged & originally
well wrought but now shrunken a good deal.

Fastenings.

If Sheathed,
Doubled, or
Felted.

Copper - Sheathed with broad sea Borradale Felt and
Coppered 1828 - 6 Breast Hooks - No cutch or winter abaft.

Repairs.

Reported to have had new Wales, Topsides and large repairs
in 1828, which is apparently correct. Two ~~old~~ Hold Beams
at the present time & Copper repaired -

at McDermott's as in
inspected the above ship 20th Sept. The 2 beams removed to above
has now been replaced with new one has all the other
other a short clamp or Chock about three feet long over the
head of Pillar

REMARKS

General Observations
and Opinion as
required by the
Instructions.

This Ship appears dry and sound at the extremities
and is firm in her general appearance without any
appearance of rot or decay and I am of opinion that
she is in an efficient state of repair for the safe conveyance
of dry and perishable cargoes & should be classed

Surveyed in Dock

At George Douglas Two Bilge Pumps

The Amount of the Fee, £ 2 : 2 : 0 is received by me.

Committed Minute 24 Sept 1834

Character signed A. 1.

Wm. C. B. H. S.



© 202

Lloyd's Register
Foundation