

ANNUAL SURVEYS.

1912
RA

No. 550 Survey held at London Date Oct 27th 1835
 on the Schooner Johnnie Master Thompson
 Tonnage 120 Built at Aberdeen When built 1827
 By whom built _____ Owners Johnnie & Co
 Port belonging to London Destined Voyage St Helena
 If Surveyed Afloat or in Dry Dock Way Dock

Original Survey, No. 305 Port of London August 1834 Classed QA1

The Surveyor is required to state the present Condition of the

Decks	<u>Good condition</u>	Breasthooks	<u>Good condition</u>	Capstan	<u>u</u>
Upper Deck Beams & Fastenings	<u>"</u>	Transoms	<u>"</u>	Pumps	<u>Good condition</u>
Lower Deck Beams & Fastenings	<u>"</u>	Timbers of the Frame	<u>"</u>	Masts, Yards, &c.	<u>"</u>
Spirketting	<u>"</u>	Topsides	<u>"</u>	Sails	<u>"</u>
Plank Shears	<u>"</u>	Wales	<u>"</u>	Cables	<u>"</u>
Waterways	<u>"</u>	Plank and Treenails (Outside to the Water's Edge)	<u>"</u>	Anchors	<u>"</u>
Hatchway Comings	<u>"</u>	Rudder	<u>"</u>	Standing & Running Rigging	<u>"</u>
		Windlass	<u>"</u>		

General Observations and Opinion,
as required by the Instructions,

Overhauling Rigging & repairing Yellow metal which
appears to have worn tolerably well to the present time &
is now in good condition - In my opinion should remain
Classed QA1
George Bayley

Committee Minute 3 November 1835

Character assigned Continue Class
RA

No. 312 Survey held at London Date November 2nd 1835
 on the Brig Richmond Hill Master B Forest
 Tonnage 234 Built at New Brunswick When built 1828
 By whom built _____ Owners Davidson & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dry Dock

RA

Original Survey, No. 892 Port of London May 1834 Classed E1

The Surveyor is required to state the present Condition of the

Decks	<u>Good condition</u>	Breasthooks	<u>Good condition</u>	Capstan	<u>u</u>
Upper Deck Beams & Fastenings	<u>"</u>	Transoms	<u>"</u>	Pumps	<u>Good condition</u>
Lower Deck Beams & Fastenings	<u>"</u>	Timbers of the Frame	<u>"</u>	Masts, Yards, &c.	<u>"</u>
Spirketting	<u>"</u>	Topsides	<u>"</u>	Sails	<u>"</u>
Plank Shears	<u>"</u>	Wales	<u>"</u>	Cables	<u>"</u>
Waterways	<u>"</u>	Plank & Treenails (Outside to the Water's Edge)	<u>"</u>	Anchors	<u>"</u>
Hatchway Comings	<u>"</u>	Rudder	<u>"</u>	Standing & Running Rigging	<u>"</u>
		Windlass	<u>"</u>		

General Observations and Opinion,
as required by the Instructions,

At the present time caulked from the keel up - and
the copper repaired -
George Bayley

Committee Minute 3 November 1835

Character assigned Continue Class
RA



© 2019

Lloyd's Register
Foundation