

REPORT of SURVEY for REPAIRS.

No. *2676* Survey held at *London* Date *30th July* 18*36*
 on the *Sp Alfred* Master *Thos. P. P. P.*
 Tonnage *716* Built at *Chelmsford* When built *1818*
 By whom built *London* Owners *Thos. P. P. P.*
 Port belonging to *London* Destined Voyage *London*
 If Surveyed Afloat or in Dry Dock *W. H. H. H.*

Original Survey, No. *1238* Dated *1835* *AEI*
 Port *London*

Repairs. *At the present time anchored from the upper
 up all new lower rigging*

The Surveyor to state the present Condition of
 Upper Deck Fastenings *are firm*
 Spirketting *is good*
 Plank Shears *do do*
 Topsides *do do*
 Upper Deck with its Appendages *In good Condition*
 Lower Deck Fastenings *are firm*

Wales *In good Condition*
 Counter *do do*
 Plank and Treennails *do do*
 (Outside to the Water's Edge.)
 Rudder *do do*
 Windlass *do do*
 Capstan *In good Condition*

General Observations and Opinion, *The Ship is in good Condition must
 as required by the Instructions, overhauled and new lower rigging to have
 a new House and her equipment will be complete
 and may be continued as classed*

The Amount of Fee..... £ : : is received by me.

Committee Minute *9 August* 18*36*

Character assigned *Continued Class*

