

2858
JH

REPORT of SURVEY for REPAIRS.

No. 2858 Survey held at London Date Sept 20th 1836
 on the Bark Hector Master W Morgan
 Tonnage 293 Built at Bristol When built 1834
 By whom built _____ Owners G Lord
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Messrs Curling Ho^r Day Dock

Original Survey, No. 1891 Dated 1835 Class A-1
 Port London

Repairs. At the present time in consequence of damage, stripped
 Caulked from keel to wale Wood sheathes Felted & coppered
 5 Plank shifted in the Starboard Quarter

The Surveyor to state the present Condition of

Upper Deck Fastenings _____	Wales _____
Spirkettling _____	Counter _____
Plank Shears _____	Plank and Treennails _____ (Outside to the Water's Edge)
Topsides _____	Rudder _____
Upper Deck with its Appendages _____	Windlass _____
Lower Deck Fastenings _____	Capstan _____

General Observations and Opinion, as required by the Instructions,
The Sunders seen about when plank was shifted are sound & in good condition, Her general appearance is favorable & in my opinion she should be classed
F. 1
George Bayley

The Amount of Fee £ 1 : 1 : 0 is received by me. at the Office

Committee Minute 14 October 1836

Character assigned Recent Repairs Venturing Class F. 1

