

2903

REPORT of SURVEY for REPAIRS.

No. 2703 Survey held at London Date Oct 21 1836
 on the Bark Ada Master Simpson
 Tonnage 311 Built at Yarmouth When built 1825
 By whom built _____ Owners Beckford
 Port belonging to London Destined Voyage Samaria
 If Surveyed Afloat or in Dry Dock Gun Dock

Original Survey, No. 997 & 2516 Dated 1834 Classed 10A new B
 Port London

Repairs. At the present time new upper piece of stem and
 upon ~~the~~ knee of the Head Cheeks & Rails - several
 planks shifted under each quarter. One new Hawse
 Piece. Breast Hooks all rebolted below. New Breast Hook
 under the Bowsprit. New Bowsprit Beam & Cornings
 to Foremast. and the Hull generally overhauled
 caulked from keel to wale and coppered upon Paper
 part of the Counter shifted

The Surveyor to state the present Condition of

Upper Deck Fastenings _____
 Spirketting _____
 Plank Shears _____
 Topsides _____
 Upper Deck with its Appendages _____
 Lower Deck Fastenings _____

Wales _____
 Counter _____
 Plank and Treenails _____
 (Outside to the Water's Edge.)
 Rudder _____
 Winlass _____
 Capstan _____

General Observations and Opinion, Timbers seen afloat - well squared and sound
 as required by the Instructions, she appears to have been originally a well
built vessel & is now put into efficient
repair
George Bayley

The Amount of Fee.....£ 2 : 2 : 0 is received by me. at the Office

Committee Minute 28 October 1836

Character assigned Record Repairs Continuum Class B
Mr. D. J. D.