

REPORT of SURVEY for REPAIRS.

No. 3311 Survey held at London Date March 18 1877
 on the Ship Attenuis Master Sparks
 Tonnage 112 Built at Wokington When built 1830
 By whom built Halli Owners Sparks
 Port belonging to Whitehaven Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Rottenburgh Dry Dock

Original Survey, No. 2088 Dated Decr - 1835 Class 9A1
 Port London

Having been asked
Repairs. *At the present time Stipples - The turnails in the upper and
 shifts Carried from keel to bottom of beam & occupied
 in paper - generally overhauled*

The Surveyor to state the present Condition of

Upper Deck Fastenings _____	Water _____
Spirkettling _____	Counter _____
Plank Shears _____	Plank and Trencails (Outside to the Water's Edge) _____
Topsides _____	Rudder _____
Upper Deck with its Appen'lages _____	Winlass _____
Lower Deck Fastenings <u>Good & tight & secure</u>	Capstan _____

General Observations and Opinion. *In my opinion the ship should remain class'd*
 as required by the Instructions, 9A1

George Bayley

The Amount of Fee 2 2s - is received by me, the
 Committee Minute 25 April 1877
 Character assigned 9A1

Lloyd's Register
 Foundation

Specimen 2. 14. 4