

REPORT of SURVEY for REPAIRS.

No. 3487 Survey held at London Date June 16 1857
 on the Ship Helms Master Lindley
 Tonnage 558 Built at Calcutta When built 1824
 By whom built _____ Owners Gibb & Co
 Port belonging to Liverpool Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock Fitchie Dry Dock

Original Survey, No. 1406, & 2510 Dated _____ 183 A. 1

Port London

Repairs. At the present time the Wrot sheathing spoiled and caulked - listers taken out of keel beam and the hoodings - the lower deck requires caulking ^{about} and left a notice recommending it to be caulked which is engaged to be done -
is repaired at the present time

The Surveyor to state the present Condition of

Upper Deck Fastenings _____
 Spirketting _____
 Plank Shears _____
 Topsides _____ Good
 Upper Deck with its Appendages _____
 Lower Deck Fastenings _____

Wales _____
 Counter _____
 Plank and Treennails _____
(Outside to the Water's Edge)
 Rudder _____ Good
 Windlass _____
 Capstan _____

General Observations and Opinion. Masts, Rigging & sails to good & efficient
This ship is in a good and efficient condition
 as required by the Instructions. In my opinion it is to be classed

*A
George Bayley

The Amount of Fee £ 3 : 3 : 0 is received by me. H. H.

Committee Minute June 22 1857

Character assigned A. 1 Asterisk J. P.