

3516

# REPORT of SURVEY for REPAIRS.

*MA*

No. 3506 Survey held at LONDON Date July 24<sup>th</sup> 1837  
 on the Spello Master Miles  
 Tonnage 219 Built at Dorchester When built 1827  
 By whom built A. Piston Owners J. Miller  
 Port belonging to LONDON Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Newsons Dock

Original Survey, No. 5138/1634 Dated 1835 Clayes 12 1831  
 Port LONDON

### Repairs.

*At the present time Shupper bottom cracked through  
 commenced it only beyond shifting and was repaired.*

The Surveyor to state the present Condition of

|                                      |   |
|--------------------------------------|---|
| Upper Deck Fastenings _____          | Wales _____   |
| Spirkettling _____                   | Counter _____   |
| Plank Sheers _____                   | Plank and Treennails<br><small>(Outside to the Water's Edge.)</small> _____ |
| Topsides _____                       | Rudder _____  |
| Upper Deck with its Appendages _____ | Winlass _____   |
| Lower Deck Fastenings _____          | Capstan _____   |

*Equipment complete*

General Observations and Opinion,  
 as required by the Instructions,

*The timbering & Planking is in the best condition  
 and the fastenings appear to be tolerable  
 as above.*

The Amount of Fee ..... £ 1. 1. - is received by me, W. Miller

Committee Minute \_\_\_\_\_ 1837

Character assigned 12 A 1



© 2019

Lloyd's Register  
 Foundation

*J. Miller*