

ANNUAL SURVEYS.

3634

No. 3634 Survey held at London Date Sept 29 1837
 on the Steamship Royal Victoria Master Chile
 Tonnage 354 Built at Leith When built 1835
 By whom built Penzance Owners Chengiz
 Port belonging to Leith Destined Voyage Leith
 If Surveyed Afloat or in Dry Dock Afloat in Petchen Drydock

Original Survey, No. 168 Port of Leith & London No. 2990 Classed 8A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks <u>Good</u>	Captain
Upper Deck Beams & Fastenings <u>"</u>	Transoms <u>"</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>"</u>	Masts, Yards, &c. <u>"</u>
Spirketting <u>"</u>	Topsides <u>"</u>	Sails <u>"</u>
Plank Shears <u>"</u>	Wales <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treennails <u>"</u> (Outside to the Water's Edge)	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>"</u>
	Windlass <u>"</u>	Copper <u>Up</u>

General Observations and Opinion, At the present time has been fixed at the waterline
 as required by the Instructions, to increase her stability. Is throughout in good condition
and in my opinion have been classed 8A according to
the rules when built

Committee Minute 6 Oct 1837
 Character assigned 8A1
George Bayley
W. G. & Co.

No. 300 Survey held at London Date Sept 29 1837
 on the Ship Chicanda Master Comble
 Tonnage 300 Built at Bristol When built 1828
 By whom built Broomfield Owners Broomfield
 Port belonging to London Destined Voyage West Indies
 If Surveyed Afloat or in Dry Dock Dry Dock

Original Survey, No. 300 Port of London & No. 97 Plymouth Classed 10A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks <u>Good</u>	Captain
Upper Deck Beams & Fastenings <u>"</u>	Transoms <u>"</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>"</u>	Masts, Yards, &c. <u>"</u>
Spirketting <u>"</u>	Topsides <u>"</u>	Sails <u>"</u>
Plank Shears <u>"</u>	Wales <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank & Treennails <u>"</u> (Outside to the Water's Edge)	Anchors No. of <u>3BA/SA/KA</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Burbaled</u>
	Windlass <u>"</u>	Copper <u>Up</u>

General Observations and Opinion, The condition of this ship is such as in my
 as required by the Instructions, opinion to entitle her to remain classed 10A1

Committee Minute 6 Oct 1837
 Character assigned 10A1
George Bayley