

REPORT of SURVEY for REPAIRS.

No. 3732 Survey held at London Date Nov 19th 18 34
on the MS Isabella Master Kinson
Tonnage 323 Built at Whitby When built 1824
By whom built _____ Owners A. Wilson
Port belonging to London Destined Voyage Robert Town
If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 1175820 Dated _____ Classed NA 1
Port London & Plymouth LD 195

Repairs At Plymouth in April last new-fellows & hammers to ballast
mark - new keel under the hold beams caulked all over,
At the present time copper raised & put new Paul bit

The Surveyor is also required to state the present Condition of the

Decks <u>Sufficiently good for the present</u>	Transoms _____	Windlass _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Capstan _____
Lower Deck Beams & Fastenings _____	Topsides _____	Pumps _____
Spirkettling <u>In good</u>	Wales _____	Masts, Yards, &c. <u>Sufficient</u>
Plank Shears <u>Condition</u>	Counter <u>In good</u>	Sails <u>and good</u>
Waterways _____	Plank & Treennails <u>Condition</u>	Cables _____
Hatchway Comings _____	(Outside to the Water's Edge)	Anchors No. of _____
Breasthooks _____	Rudder _____	Standing & Running Rigging _____
	Copper _____	

General Observations and Opinion, This ship is good and sound in every visible part
as required by the Instructions, except her masts which are not so good as they should
be for their age, but are at present tight and in my
opinion sufficient for her present intended voyage
and she may be continued as classed.

The Amount of Fee.....£ 2 : 2 : - is received by me, for Office
Committee Minute Nov 5 1834
Character assigned Continued