

ANNUAL SURVEYS.

7-3538

No. 3038 Survey held at LONDON Date Nov 29 1877
 on the "Edna" Master _____
 Tonnage 314 Built at LONDON When built 1876
 By whom built Hutchins & Co Owners Homes
 Port belonging to LONDON Destined Voyage _____
 If Surveyed Afloat or in Dry Dock: Hutchins & Co

Original Survey, No. 10030264 Port of LONDON Classed 2 A 1

The Surveyor is required to state the present Condition of the

Decks _____	Breasthooks _____	Copstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. <u>New lower masts</u>
Spirkettling _____	Topsides _____	Sails <u>2 duty</u>
Plank Shears _____	Wales _____	Cables <u>Three chains</u>
Waterways _____	Plank and Treenails (Outside to the Water's Edge) _____	Anchors No. of <u>3 B & 4 K</u>
Hatchway Coverings _____	Rudder _____	Standing & Running Rigging <u>good</u>
	Windlass _____	Copper <u>up and</u>

General Observations and Opinion. Now worked from the top of and generally
 as required by the Instructions, overhauled, is throughout in the best condition
and may be continued in service, Houtman

Committee Minute 2 days 1877

Character assigned 2 A 1
C.G.

No. 308 Survey held at LONDON Date Nov 30th 1877
 on the "La Pierre mere" Master _____
 Tonnage 296 Built at New Brunswick When built 1825
 By whom built _____ Owners Gilins &
 Port belonging to LONDON Destined Voyage Antwerp
 If Surveyed Afloat or in Dry Dock: afloat

Original Survey, No. 1152, 1246 Port of LONDON Classed B 2
3704 & 3694

The Surveyor is required to state the present Condition of the

Decks <u>The water part has</u>	Breasthooks _____	Copstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. <u>Support good</u>
Spirkettling _____	Topsides _____	Sails _____
Plank Shears _____	Wales _____	Cables <u>2 New Chain, Collie of</u>
Waterways _____	Plank & Treenails (Outside to the Water's Edge) _____	Anchors No. of <u>modern 540 King's</u>
Hatchway Coverings <u>the</u>	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper _____

General Observations and Opinion. about two thirds of this ship's deck used also
 as required by the Instructions, the beams are in good condition, her external
planking looks suspicious, unfit for the purpose of being pressed back,
is now supplied with new chains and they in the opinion of
be closed fit

Committee Minute 2 days 1878

Character assigned F 1
C.G.