

REPORT of SURVEY for REPAIRS.

4023

No. 1423 Survey held at London Date March 31 1838
 \$25 on the Brig Acadia Master Colls
 Tonnage 140 Built at Liverpool When built 1820
 By whom built _____ Owners Phillips
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Fitted Dry Dock

Original Survey, No. 1802, 2604 & 3447
 Port London

1836 Classed A.1
 1837

Repairs

At the present time in consequence of damaged several knees
 shifted and holdstems knees additionally rotten. Some of the
 three stake shifts forward (2 Planks) - Cashed from the
 Copper up and all the damage efficiently repaired & made
 good -

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Top-sides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,
 as required by the Instructions,

In my opinion this ship is now in a condition to
 remain clasped A.1

John Dayley

The Amount of Fee £ 10 : 11 is received by me John Dayley

Committee Minute March 1838

Character assigned A.1 Antony reced San. rep
Am

Special for damage £2.2 13/6

LOAN 602-0278