

# REPORT of SURVEY for REPAIRS.

No. 4208 Survey held at London Date May 29 1838  
 on the Schooner Coward Master Martin  
 Tonnage 141 Built at Plymouth When built 1832  
 By whom built \_\_\_\_\_ Owners Palmer  
 Port belonging to London Plymouth Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock William's Quay Dock

Original Survey, No. \_\_\_\_\_ Dated \_\_\_\_\_ 1834 Classed 12 A 1  
 Port London

Repairs at the present time caused from the keel up  
and copper to top of

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, This vessel is now in an efficient state of repair  
 as required by the Instructions,

The Amount of Fee.....£ : : is received by me,

Committee Minute ..... 18

Character assigned See annexed Survey