

REPORT of SURVEY for REPAIRS.

4320

No. 4320 Survey held at London Date July 13 1858
 on the Ship Alfred Master Tappley
 Tonnage 716 Built at Chittagong When built 1848
 By whom built _____ Owners Flint
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Blackett's Dock

Original Survey, No. 1238, 2676 Dated 1836 Classed A.1
 & 3446 1837 *A.1
 Port London

Repairs At the present time stipples caulked from the keel up—partially hung (abaft) part new false keel sheathed with yellow metal to the ^{middle of the} rails. Hordings luted with metal

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

Condition of Decks, Transoms, Windlass, Capstan, Pumps, Masts, Yards, &c., Sails, Cables, Anchors, Standing & Running Rigging: Good

General Observations and Opinion, as required by the Instructions, My opinion this vessel is fully entitled to remain classed *A.1

George Bayley

The Amount of Fee.....£ 1 : 1 : — is received by me, HA

Committee Minute 24 July 1858

Character assigned A.1 Certificate - wood repairs