

REPORT of SURVEY for REPAIRS.

No. 4328 Survey held at London Date July 9 1838
 on the Ship Marley Master Evans
 Tonnage 492 Built at London When built 1811
 By whom built _____ Owners Heath
 Port belonging to London Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock Blackwall Dock

Original Survey, No. 3171 Dated Feb 1837 Classed A.1
 Port London

Repairs At the present time in consequence of damage 3 lower Deck Beams shifted - Head refitted, Birlhing of Stern refastened 6 pair of Iron Hanging Standards fitted to lower Deck a number of Standard Bolts shifted, Caulked keel up and recoppered to the Wale - A Plank of the Ceiling taken out on the Starboard side at the 1st Head. Timbers good and the outside plank close to the Timbers -
 All the damage efficiently repaired

The Surveyor is also required to state the present Condition of the

Upper Deck Beams & Fastenings	Transoms	Windlass
Lower Deck Beams & Fastenings	Timbers of the Frame	Capstan
Spirketting	Topsides	Pumps
Plank Shears	Wales	Masts, Yards, &c.
Waterways	Counter	Sails
Hatchway Comings	Plank and Treenails (Outside to the Water's Edge)	Cables
Breasthooks	Rudder	Anchors No. of
	Copper <u>Asst</u>	Standing & Running Rigging

General Observations and Opinion, *In my opinion this Ship is fit for the conveyance of dry and perishable cargoes to and from all parts of the world and should be classed A.1*

George Bayley

The Amount of Fee.....£ 2 : 2 : - is received by me, *AS*

Committee Minute 24 July 1838

Character assigned A.1 *Asst*