

REPORT of SURVEY for REPAIRS.

No. 4580 Survey held at London Date Oct 24 18 38
on the Bark Foughton Master Shinnels
Tonnage 282 Built at Shivers When built 1826
By whom built _____ Owners Coats
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock In & aft Dry Dock.

Original Survey, No. _____ Dated April 1837 Classed A.1
Port London

Repairs *at the present time stripped and had keel
up, broosheathed on Telt^{in 1837} of coppered to
11 ft in*

The Surveyor is also required to state the present Condition of the

| | | |
|-------------------------------|--|----------------------------|
| Decks | Transoms | Windlass |
| Upper Deck Beams & Fastenings | Timbers of the Frame | Capstan |
| Lower Deck Beams & Fastenings | Topsides | Pumps |
| Spirkettling | Wales | Masts, Yards, &c. |
| Plank Shears | Counter | Sails |
| Waterways | Plank and Treenails (Outside to the Water's Edge) | Cables |
| Hatchway Comings | Rudder | Anchors No. of |
| Breasthooks | Copper <u>1838</u> | Standing & Running Rigging |

General Observations and Opinion,
as required by the Instructions,

*In my opinion this Rept is eligible
Ground in in her present class A.1*

George Bayly

The Amount of Fee.....£ : : is received by me,

Committee Minute _____ 18 _____

Character assigned See annexed Survey